



Service	Price
Universal Service	
Bearing Replacement	\$ 15.00
Heavy Cleaning	\$ 20.00
OEM Mount Removal	\$ 50.00
Lower Eyelet Replacement	\$ 25.00
Fox 2.0 Performance Series Shocks	
Pre-Rebuild Inspection*	\$ 40.00
Rebuild Labor	\$ 85.00
Spring Removal	\$ 25.00
Re-Valve - To AccuTune Valve Code	\$ 50.00
Air Shock/Air Bump/Coilover/Smoothie	
Pre-Rebuild Inspection*	\$ 40.00
Rebuild Labor	\$ 75.00
Spring Removal	\$ 20.00
Re-Valve - AccuTune Calcs & Labor	\$ 65.00
AccuTune Valving, Calculations Only	\$ 50.00
Re-Valve - Labor Only	\$ 35.00
Bypass - External	
Pre-Rebuild Inspection*	\$ 60.00
Rebuild Labor	\$ 125.00
Re-Valve - AccuTune Calcs & Labor	\$ 80.00
AccuTune Valving, Calculations Only	\$ 65.00
Re-Valve - Labor Only	\$ 50.00
Bypass - Internal & Raptor	
Pre-Rebuild Inspection*	\$ 45.00
Rebuild Labor	\$ 90.00

*Inspection fee to be applied to rebuild cost if work is performed at AccuTune Off-Road.

*Inspection includes disassembly, recycling of oil, and inspection of components necessary to estimate repair cost. Does not include re-assembly or oil re-fill.

Updated: 11/2/16