



| Service | Price |
|---|-----------|
| Universal Service | |
| Bearing Replacement | \$ 15.00 |
| Heavy Cleaning | \$ 20.00 |
| OEM Mount Removal | \$ 50.00 |
| Lower Eyelet Replacement | \$ 25.00 |
| Fox 2.0 Performance Series Shocks | |
| Pre-Rebuild Inspection* | \$ 40.00 |
| Rebuild Labor | \$ 85.00 |
| Spring Removal | \$ 25.00 |
| Re-Valve - To AccuTune Valve Code | \$ 50.00 |
| Air Shock/Air Bump/Coilover/Smoothie | |
| Pre-Rebuild Inspection* | \$ 40.00 |
| Rebuild Labor | \$ 75.00 |
| Spring Removal | \$ 20.00 |
| Re-Valve - AccuTune Calcs & Labor | \$ 65.00 |
| AccuTune Valving, Calculations Only | \$ 50.00 |
| Re-Valve - Labor Only | \$ 35.00 |
| Bypass - External | |
| Pre-Rebuild Inspection* | \$ 60.00 |
| Rebuild Labor | \$ 125.00 |
| Re-Valve - AccuTune Calcs & Labor | \$ 80.00 |
| AccuTune Valving, Calculations Only | \$ 65.00 |
| Re-Valve - Labor Only | \$ 50.00 |
| Bypass - Internal & Raptor | |
| Pre-Rebuild Inspection* | \$ 45.00 |
| Rebuild Labor | \$ 90.00 |

*Inspection fee to be applied to rebuild cost if work is performed at AccuTune Off-Road.

*Inspection includes disassembly, recycling of oil, and inspection of components necessary to estimate repair cost. Does not include re-assembly or oil re-fill.

Updated: 11/2/16